
# **Robot Tool Changers** | | **SWA100**





	Master Adaptor	1 001 Adaptor
Reference	G-SWA100- 2O	G-SWA100- 2U
Payload	80 kg	
Moment - Mx, My	1500 Nm	
Moment - Mz	219 Nm	
Repeatability - X, Y	0.020 mm	
Maximum Axial Tensile Force (no damage if exceeded)	Al, Anod.	



## **Operating conditions**

Operating temperature 5-60°C Operating pressure 6 bar  $\pm 1$  User pneumatic pressure 6 bar  $\pm 1$ 

# **Extreme Compactness for uncompromising flexibility with the SWA Connector**

Our manual tool changers range aims at solving quick equipment change issues for many applications. These tool changers can be seen as quick, repeatable, and reliable mechanical connectors that can serve many purposes: robot tooling change, special machinery utility change or even making a tool stand movable. Installing such a kind of quick connection device makes your equipment versatile, and upgradable, and eases

maintenance operation while reducing downtimes.





#### Renefit

### Advantages

- Withstands high loads with low dead weight
- Can be released and closed with one handle
- During locking, the lower assembly is pulled around the locking stroke
- Interface according to DIN EN ISO 9409-1

- Does not require a deep review of the echanical structure to be integrated.
- Cost savings through reduced maintenance downtime.
- Improved equipment versatility and upgradability and then extended productivity.
- Mitigate the need of specifically designed mounting interfaces



## expertise in connectivity